COMPLETION REPORT

1. Name of Work : **IMPROVEMENTS AND ASPHALTING TO 10TH CROSS (BETWEEN 8TH MAIN AND PIPELINE ROAD) BHUVANESHWARI NAGARA IN BAGALAGUNTE WARD NO.14 DASARAHALLI SUB DIVISION**

3. Head of Account which is Chargeable : ಡಿ-ಎಸ್ 1221

4. Entrustment Order No. & Dt. :

5. Name of Contractor : **SRI.K.JAGADISH**

6a. Time stipulated for completion of work :

b. Delay in Execution of work :

7. Measurement recorded in : M.B.No. 5692/16-17

Page No. 56713 to 56717

1. Check measurement of the Asst. : M.B.No. 5622/16-17

Page No. 56713 to 56717

9. Name of the Office / Official :

In charge of the work :

10. a) Asst. Eng/ Junior Eng. : ಡಿ-ಎಸ್-ಎಂಜಿನಿಯರ್

b) Asst. Exe. Engineer : ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ

Sanctioned estimate amount	Amount claims as per actually vide as per bills	DIFFERENCE	
		Excess	Savings
20.nbey	177683 ನ	-	22312

1. Certified that the above work has been completed within the stipulated time noted in the work order.
2. Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3. Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

ASST. ENGINEER
W.14

ASST.EXE.ENGINEER
T.DASARAHALLI SUB DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

ACCOUNTS SUPTD.
DASARAHALLI DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Division, Bangalore-57.